

RECEIVING INSPECTION REPORT

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080007-6

2961 E. COLORADO ST., PASADENA, CALIF.

RECEIVED FROM

DATE REC'D. 1-24-57

P.O. NO.

VENDOR PACKING SLIP NO.

CHANGE TO QUANTITY RECEIVED	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	ACCT. OR W.O. NO.	REMARKS
	DRAWING NO. AND DESCRIPTION							QUANTITY		
12	322	000000	12138	0	0	00	00			
	731267 -1 ROCKER CLUTCH							12	✓	
	SHIP MEMO 85840									
	TO SUPERSEDED 128114									

RECEIVED BY

INSPECTED BY

DATE

REJECTS RETURNED
ON SHIP MEMO NO.

RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

2961 E. COLORADO ST., PASADENA, CALIF.

No. 11024

RECEIVED FROM

DATE REC'D. 1-24-57

P.O. NO.

VENDOR PACKING SLIP NO.

CHANGE TO QUANTITY RECEIVED	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	ACCT. OR W.O. NO.	REMARKS
	DRAWING NO. AND DESCRIPTION							QUANTITY		
12	322	000000	12138	0	0	00	00			
	731267-2 ROCKER CLUTCH							12	✓	
	SHIP MEMO 85840									
	TO SUPERSEDED 128115									

RECEIVED BY

INSPECTED BY

DATE

REJECTS RETURNED
ON SHIP MEMO NO.

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080007-6

HMC-1069